Qty:

20 Um:

Each

Tuesday, 30/09/2008 8:55:26 AM

User:

Julie Lecocq

#### **Process Sheet**

**Drawing Name** 

**Part Number** 

Material **Due Date** 

**Drawing Number** 

**Project Number** 

**Drawing Revision** 

: WEARPAD

: D35371

: N/A

: C

: D3537 REV C

: 15/10/2008

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**  : 42351

S.O. No. :

P.O. Number

: 30/09/2008 This Issue

: NC Prsht Rev.

First Issue **Previous Run**  : //

: 42235

: 12712

: SMALL /MED FAB Type

Written By **Checked & Approved By** 

Comment

: Est Rev:A New Issue 07-02-14 JLM

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

304/316 Sheet .063

1.0 M304S16GA

Comment: Qty.: 0.1113 sf(s)/Unit Total: 2.2260 sf(s)

M304S16GA .063" 304 SS SHEET

10965 Batch:

WATER JET 2.0

FLOW WATER JET



Comment: FLOW WATER JET 1-Cut as per Dwg D3537

> Dwg Rev: C Prog Rev:\_\_

B8-10-27

2-Deburr if necessary

1B8-10-27

3.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE



B8-10-27

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



Comment: SECOND CHECK

BRAKE NC 5.0

NC BRAKE





Comment: NC BRAKE

1-Form as per Dwg D3537 on CNC brake using Jigs DT 8261 and DT 8326.

2-Identify as D3537-1





Dart Aer	ospace	Ltd
----------	--------	-----

							!				
W/O:			= + 7	W	ORK ORDER	CHANGES					H
DATE	STEP		PROC	EDURE CH	IANGE		By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
. 0										*	
	,		Q E			*					
Part No	:	P	AR #:	_ Fault Ca	tegory:	NO	CR: Yes	No DQ	A:	_ Date: _	
	R	esolution:									
NCR:			W	ORK OR	DER NON-CO	NFORMANC	E (NC	R)		-4	, A
5475	0.750	Description of NC		Corrective Action Section B			j	Verific	ation	Approval Chief Eng	Approval
DATE	STEP	Section	A 2-387	Initial Chief Eng				Sign & Section C			QC Inspector
						275 (24)		***		#*	
			¥				· s				
			÷								
	-	7		·				,			
	¥	7. 		4.		ė.					
								7.7			.0.

NOTE: Date & initial all entries

Date: Tuesday, 30/09/2008 8:55:26 AM User: Julie Lecocq **Process Sheet** Drawing Name: WEARPAD Customer: CU-DAR001 Dart Helicopters Services Job Number: 42351 Part Number: D35371 Job Number: Seq. #: Description: **Machine Or Operation:** LARGE FAB 1 LARGE FABRICATION RESOURCE 1 6.0 Comment: LARGE **FABRICATION RESOURCE 1** Qty Description Batch-A/R <u>m109363</u> 2059B Hardcoat 1-Weld as per Dwg D3537 using Jig DT 8210 2-Remove any weld that penetrated through Wearpadif necessary 7.0 QC10 VISUAL INSPECTION OF GROUND WELDS Comment: VISUAL INSPECTION OF GROUND WELDS INSPECT WORK TO CURRENT STEP 8.0 QC5 Comment: INSPECT WORK TO CURRENT STEP POWDER COATING 9.0 POWDER COATING M 106442 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 START TIME: OVEN TEMPERATURE FINISH TIME: 10.0 QC3 INSPECT POWDER COAT/CHEMICAL CON Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 11.0 **PACKAGING** PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 12.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion

### Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANG	ES					
DATE	STEP		PROCEDURE CHAI	CEDURE CHANGE			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			#			1				
						r I				
		j *				+	ļ			
		, 3 1				ì				
		; ;				1			e e	
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _		
	Reso	olution:	Dispositio	Disposition: QA: N/C Closed: Date:						
NCR:				ER NON-CONFORMA						
DATE	STEP Descrip	Description of NC		on B		cation	Approval	Approval		
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	on C	Chief Eng	QC Inspector	
		3.0	-		(C)					
		1				e I				
-						i į				
		1.				ļ.				
		1,1				i C				
<del></del>		i '		,	j.					
		1				1				
		. ( · ·				1				
		ė			:					

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order: 4236
Description: Wearpad	Part Number: D3537-1
[14]	
Inspection Dwg: D3537 Rev: C	Page 1 of 1


## FIRST ARTICLE INSPECTION CHECKLIST


•	, <b>X</b>	First Article	Prototype
		Antural	


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
4.250	+/-0.010	4.247	18-			
3.500	+/-0.010	3,498	×		-	
1.965	+/-0.010	1.966	*			1.8
2.795	+/-0.010	2.790	*		ě.	
3.625	+/-0.010	3,624	<b>y</b>			
0.220 x 0.380	+/-0.010	234 X.383	\$			
4.	9					
+	A				÷	
,						
			• ,			- 1 - 1
			E) -			2 000
	~		-1-			
	,			-		.*
	(4)					
						·

Measured by:	Audited by:	Prototype Approval:	N/A
Date: \$-10-57	Date: 08/10/27	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.03.21	New Issue	KJ/JLM	
В	07.04.27	Dimensions revised per Dwg Rev. B	KJ/JLM	1
С	07.05.28	Dimensions revised per Dwg Rev. C	KJ/JLM	ad








## D3537-3 LONGITUDINAL BEND (MADE FROM D3537-3F)

# D3537-5 LONGITUDINAL BEND (MADE FROM D3537-1F)



## D3537-1/-3/-5/-7 WEARPAD NOTES

- 1) MATERIAL: AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524, 16 GAUGE (0.063 THICK) (REF DART SPEC. M304S16GA)
- 2) BREAK ALL SHARP CORNERS 0.063 MAX
- 3) WELD PER QSI 004


0.25

(TYP)


- 4) FINISH: POWDER COAT GREY SANDTEX (4.3.5.6) PER QSI 005 4.3
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 6) ALL DIMENSIONS ARE IN INCHES



SECTION A-A



### SECTION B-B



D3537-7 LONGITUDINAL BEND 962

(MADE FROM D3537-3F)

A SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED OPY
SHBIECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 435

			0.00							~~
	С		07.0	4.13	WIDE	N TAB T	0 0.38	30, WELD	PATTER	RN
	B 07.03.20		3.20	ADD AMS 5513 AND AMS 5524						
	Α		06.1	1.06	NEW	ISSUE				
NC.	DESIG	ر ه	DRAWN	PH	DA	IRT	DART	AEROSPAC PORT HADLOS	E USA,	INC.
	CHECK	ED A	APPROVE	D d	DRAWING					REV. C
SE :		91	į	9	D3537	7			SHEET	1 OF 1
	DATE		1		TITLE					SCALE
	07.0	4.13			WEARF	PAD				1:2

0.25

(TYP)

## COPYRIGHT @ 2006 BY DART AEROSPACE USA, IN

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

